

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L79	1657	((metal) with (base or plate or substrate)) with (hole or cavity or hollow\$)) and semiconductor	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:10			0
2	BRS	L80	566	257/669.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:41			0
3	BRS	L81	562	L80 not L79	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:12			0
4	BRS	L82	578	L80 not L79	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:41			0
5	BRS	L83	573	L82 not 181	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:41			0
6	BRS	L84	573	L83 not L80	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:41			0
7	BRS	L85	573	L83 not L79	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:48			0
8	BRS	L86	215	257/708.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 16:56			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
9	BRS	L87	310	257/729.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 17:47			0
10	BRS	L88	292	361/600.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 17:54			0
11	BRS	L89	50	361/746.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 17:56			0
12	BRS	L90	71	361/743.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 17:58			0
13	BRS	L91	142	361/750.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:01			0
14	BRS	L92	210	361/751.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:04			0
15	BRS	L93	141	L91 not L90	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:01			0
16	BRS	L94	1062	361/760.cc1s.	USPAT; US-PGPU; B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:16			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
17	BRS	L95	1057	194 not 179	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:06			0
18	BRS	L96	688	361/807.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:32			0
19	BRS	L97	420	438/121.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:39			0
20	BRS	L98	484	438/125.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:52			0
21	BRS	L99	443	L98 not L97	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:40			0
22	BRS	L100	603	438/123.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:52			0
23	BRS	L101	570	L100 not L99	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:52			0
24	BRS	L102	562	L101 not L98	USPAT; US-PGPU B; EPO; JPO; DERWENT ; IBM TDB	2001/12/19 18:53			0

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error rs
1	BRS	L1	1	"6261868"	USPAT 20:24	2001/12/19			0
2	BRS	L2	567	257/703.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT > IBM TDB	2001/12/19 21:09			0
3	IS&R	L3	1	("3936864") .PN.	USPAT 21:16	2001/12/19			0
4	BRS	L4	1	"3825805".PN.	USPAT 21:11	2001/12/19			0
5	BRS	L5	1	"3801938".PN.	USPAT 21:11	2001/12/19			0
6	BRS	L6	1	"3681513".PN.	USPAT 21:12	2001/12/19			0
7	BRS	L7	1	"3651434".PN.	USPAT 21:12	2001/12/19			0
8	BRS	L8	1	"3500066".PN.	USPAT 21:12	2001/12/19			0
9	BRS	L9	538	257/720.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT > IBM TDB	2001/12/19 22:00			0
10	BRS	L10	1	"3710202".PN.	USPAT 21:35	2001/12/19			0
11	BRS	L11	1	"3515952".PN.	USPAT 21:35	2001/12/19			0
12	BRS	L12	310	257/729.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT > IBM TDB	2001/12/19 22:07			0
13	BRS	L13	486	257/728.cc1s.	USPAT; US-PGPU B; EPO; JPO; DERWENT > IBM TDB	2001/12/19 22:07			0
14	BRS	L14	478	L13 not L12	USPAT; US-PGPU B; EPO; JPO; DERWENT > IBM TDB	2001/12/19 22:08			0